


Preparation for test

- 1 Remove glove box (68-140).

Connecting adapter to volt/ohm measuring instrument

- 2 Pull 12-point plug from electronic switching unit (9) for temperature control and connect to adapter. Yellow test card (issue October 1980) must be used.

9 Electronic control unit for temperature control



- 3 Connect adapter with volt/ohm measuring instrument to 12-point coupling and switch adapter to test step 1.

